

Work Order (Bid Form)

Knoxville/Knox County Community Action Committee



WORK ORDER INFORMATION

Work Order Name: WO/80008KN0344/1

Work Order Type: Weatherization

Audit Name: 80008KN0344-Audit

CLIENT INFORMATION

Client Name:

Address:

Client ID: 80008KN0344

Alt. Client ID: KNOX

AGENCY INFORMATION

Agency: Knoxville/Knox County CAC

Address: P.O.Box 51650

Knoxville, TN 37950-1650

Agency Phone: (865) 244-3080

Fax: (865) 544-1647

Email Address: jason.estes@cachousing.org

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Single Family Dwelling

Contractor to follow 2006 International Residential Code as adopted by the City of Knoxville or Knox County as applicable.

County

House built in 1940

An EPA Certified Firm/Renovator is required.

Client Name:

Client ID: 80008KN0344 Alt. Client ID: KNOX Work Order (Bid Form)

Work Order Name: WO/80008KN0344/1 Report Run On: 5/6/2010 DOE Weatherization Assistant Version 8.6.0 Page 1 of 13

Measures

Measure 1	Broken Pane 5)(N2,N3,W2,	(upto 10 squa S1,N4)	re feet) (0	YT	Componen	ts			Inspected
Comment Re	efer to Appendi eld Guide.	x A- Standards	for Weath	erizati	on Materials	and So	utheast		100
					Estimated			Actual	
# Material / Lai	bor Descripti	on / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Unspecified	Broken F square fe	ane (upto 10 eet) (+)	Each	5					
2 Labor	labor		Each	5					
Other Detail									
						N/			
] []		
				Measure	e Sub Total:		_	Sub Total:	
Fleid Notes:					1				

	Measure 2 Duc	t Insulation (Return)(8S	iF)	***************************************	Componen	ts			Inspected
C	NO GIIAI	on must be a minimum of nges allowed. Refer to Ap s and Southeast Field G	opendix A.	Stanc	ped with the	appropi	tion	pe.	
л					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Construction Mate	Duct Insulation	Linear Foot	8					
		Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.							
2	Labor	Labor	Linear Foot	8					
0	ther Detail								
]		
] <u> </u>] [] [] [] [
							<u> </u>		
Г			^	1easure	Sub Total:]	Sub Total:	
	Field Notes:						,		

	Measure	3 Sla	ab Door (D3)	***		Componen	ts		<u>.</u>	Inspected
C		deadb chose height Weath	ve old door before installing as a complete unit. A dolt, hinges, threshold, striken by homeowner or sand/sold). No changes allowed. Reprization Materials and Sold not anyone else.	oor is inclu ce plate, pa staind/seal efer to App	isive o aint(1s), peep endix	s is a slab do f weatherstri t quality sem o hole (at hor A- Standards	or. A do pping, do nigloss co meowne	oor lock plor to b desire	e e	
,,						Estimated			Actual	
#	Material /	Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Doors		Slab Door	Each	1		7.0			
2	Labor		Labor	Each	1					
C	Other Detail	***	-							
L										
	~									
				/	Measure	Sub Total:			Sub Total:	
178 to 1	Field Notes	s:							L	

Measure		indow Glazing qty 17 all ome	windows	on	Componer	its			Inspected
Commen	MeM (ose glazing must be 100% glazing should be even, sm andards for Weatherization	ooth, and	all loo	k uniform R	efer to A	nnandiv	(
	NOTE accep	E: Silicone, caulk, or any otl table.	ner produc	t that	is not windo	w glazing	is not		
					Estimated	•		Actual	
# Material /		Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Windows	3	Window Glazing	Each	17					
		Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.							
2 Labor		Labor	Each	17					
Other Detail									
			Л	/leasur	e Sub Total:		s	ub Total:	
Field Note	s:			,					

Measure 5 DV	WH Pipe Insulation			Componen	ts		1000	Inspected
Comment				•				
				Estimated	,		Actual	<u> </u>
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DHW Pipe Insulation	Each	1					
	Includes labor cost. All corners must be cut properly. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.						L,	
2 Labor	DHW Pipe Insulation	Each	1					
Other Detail								""
		1	Measur	e Sub Total:			Sub Total:	
Field Notes:	70. 70.	**						

Report Run On: 5/6/2010

	Measure 6 DWH	Tank Insulation			Componen	ts		················	Inspected
C	comment extend p	ressure relief pipe as ne	eded.		•				
					Estimated	ı		Actual	l
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equipm	DHW Tank Insulation	Each	1					
		Includes labor cost. R-10 minimum. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.			·				
2	Labor	DHW Tank Insulation	Each	1					
C	ther Detail								
L									
				Measur	e Sub Total:			Sub Total:]
	Field Notes:								

Report Run On: 5/6/2010

Measure	9 7	Floor Ins. R-19			Componen	ts F1			Inspected
Commen	Sta sub (e.g	cludes labor cost. Contra ore installing insulation. on Indards. Insulation is insulation is insulation is insulation is insulation is insulation is insulation. In staves for blankets). In pressions. Refer to App Southeast Field Guide.	Contractor to in talled to mainta against subfloon nsulation to ha	nstall u ain per or) incl ve NO	sing Resnet manent cont uding necess gaps, voids	Grade 1 act with t sary supp	he orts		
					Estimated			Actual	
# Material	/Labo	or Description / Comme	nt Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulatio	n	Floor Insulation - Fiberglass Batts - R-	SqFt 19	980					
2 Labor		Floor Insulation - Fiberglass Batts - R-	SqFt 19	980					
Other Deta				Measur	e Sub Total:			Sub Total:	

Measure 8 Du	ıct Insulation			Componen	ts			Inspected
ıape. ı	ation must be a minimum o No changes allowed. Refer als and Southeast Field G	r to Anner	st be ta	ped with the Standards for eams before	appropri or Weathe insulating	rizatio	n	
# Material / Labor	5			Estimated			Actual	
	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Duct Insulation	SqFt	106.8					
	Includes labor cost. Contractor must use a minimum of R-6 insulation. All foil tape should be free of bubbles. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.							
2 Labor	Duct Insulation	SqFt	106.8					
Other Detail								
								7/11
			Mossuro	Sub Total:		i	ub Total:	
Field Notes:	7/1			Gub Total.			ub rotai:	
Total Notes.								

Report Run On: 5/6/2010

Measure 9 F	ix Improper Venting (Cloth	es Dryer	·}	Component	ts			Inspected
Comment Dryer protru is 15	Vents installed with damper Iding through pipe. Must be feet. No changes allowed. F herization Materials and Sou	. Metal p vented to Refer to A	ipe ins outsio	talled withou le of home. N	t any fas	lonath		
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safe	ety Dryer Vent w/ Metal Piping (upto 15' in length)	Each	1		77.			
	Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.							
² Labor	Labor	Each	1					
Other Detail								
		1	/leasure	Sub Total:		s	ub Total:	
Fleid Notes:								707

Me	easure 10 Fix Exh	mproper Venting of Ba aust Fan	throom	***	Componen	ts	,o	- 10	Inspected
Con	nment Bath Ve Attachm Guide.	nts installed to outside of ent A- Standards for We	home. Ne atherizatio	o char on Ma	nges allowed. terials and Sc	Refer to outheast) Field		
					Estimated			Actual	
# Ma	aterial / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 He	ealth and Safety	Bath Vent w/ Piping to Outside	Each	1					
		Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.							
2 La	bor	Labor	Each	1					
Othe	r Detail								
			71.						
-			Λ	/leasur	e Sub Total:			Sub Total:	
Fiel	ld Notes:							do rotar.	
									j

N	<i>fleasur</i> e 11 Pra (Do	ctice Lead Safe Weath or Replacement)	erization		Componen	ts		Inspected
Co	Dmment A Certif submit activity.	fied Firm /Renovator is r copy of Lead Report ar	required to a nd 3 pictures	adhere s (befo	to EPA RRF ore, during, a	rules. Ind after)	Need to of each	
					Estimated		Actual	,
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty Unit Co	st Total
1	Health and Safety	EPA RRP Lead Rules	Each	1				
2	Labor	Labor	Each	1				
Ot	her Detail							
				Measur	e Sub Total:		Sub Total	•
F	Field Notes:	.,						
İ								
					77/		71.	
M	easure 12 Vapo	or Barrier Needed			Component	5		Inspected
_		ement/CrawIspace)(Q						
Coi	mment Must be	6 mil poly. Must be inst	alled 100%	of crav	wlspace with	6" turned	d up all	
	walis and	a support piers. Must b	e secureiv fa	astene	ed Mustherd	leated de	own to	
	Weather	ust be secured at all serization Materials and Sc	ams. Keter i Jutheast Fie	BJJA OJ	ichment A- S	tandards	for	
			Juli Jouot 1 10	na Oai	Estimated		Actual	
# M	laterial / Labor	Description / Comment	Units	Qty	Unit Cost	Total		. T-4-1
1 -	lealth and Safety	Basement /Crawlspace	SqFt	980		Total	Qty Unit Cos	t Total
	Í	Vapor Barrier	oqi €	000				
? L	abor	Labor	SqFt	980				
Oth	er Detail							
	7							· · · · · · · · · · · · · · · · · · ·
			1 11		11			
***				easuro	Sub Total:		Sub Total:	
Fle	ald Notes:		Mo	easure	Sub Total:		Sub Total:	
Fie	eld Notes:			easure	Sub Total:		Sub Total:	
Fle	eld Notes:		M	easure	Sub Total:		Sub Total:	
Fie	eld Notes:		M	easure	Sub Total:		Sub Total:	
Fle	eld Notes:		M	easure	Sub Total:		Sub Total:	
Fle	eld Notes:			10				
Fie	eld Notes:		Mork Orde	10			Sub Total:	

Client Name:

Client ID: 80008KN0344

Alt. Client ID: KNOX

Work Order (Bid Form)

Work Order Name: WO/80008KN0344/1 Report Run On: 5/6/2010 DOE Weatherization Assistant Version 8.6.0

Page 12 of 13